10/647 848

OIPE Attorney Docket No. LCB411		
APR 2 1 2006 (A) IN THE UNITED STATES PA	TENT	AND TRADEMARK OFFICE
PADEMATOR entors: Jack E. Caveney, et al.)	
U.S. Patent No.: 7,011,454)	Examiner: Chandrika Prasad
Issue Date: March 14, 2006)	Group Art Unit:
For: Reversible Fiber Optic Stub Fiber)	

REQUEST FOR CERTIFICATE OF CORRECTION UNDER 37 CFR §1.322

)

Certificate of Corrections Branch Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Connector

Certificate

APR 2 6 2006

of Correction

Dear Sir:

The applicants, through their attorneys, request the issuance of a Certificate of Correction under 37 CFR §1.322, Certificate of Correction of Office Mistake, to correct the following mistakes in U.S. Patent No. 7,000,784:

Column 10, Line 10 reads "a ring an portion for attaching" however it should read "a ring portion for attaching."

Column 11, Line 23 reads "... second cam surface a buffer clamp" however it should read "... second cam surface actuates a buffer clamp"

Attached is a copy of Form PTO/SB/44.

Respectfully submitted,

Dated: April 17, 2006

Panduit Corp. - Legal Department 17301 Ridgeland Avenue Tinley Park, Illinois 60477-3091 (708) 532-1800, Ext. 1302 Zachafy J. Smolinski Reg. No. 47,100

Attorney for Applicants

U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE
Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION


		Page1	of	1	
PATENT NO. :	7,011,454	9			
APPLICATION NO.:	10/647,848				
ISSUE DATE :	March 14, 2006				
INVENTOR(S) :	Jack E. Caveney, et al.				
It is certified is hereby correct	I that an error appears or errors appear in the above-identified patent and the ed as shown below:	at said Le	tters Pa	tent	
Column 10, Line	e 10 reads "a ring an portion for attaching" however it should read "a ring po	rtion for at	taching.	"	
Column 11, Line 23 reads " second cam surface a buffer clamp" however it should read " second cam surface actuates a buffer clamp"					
				:	

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Zachary J. Smolinski, Panduit Corp. Legal Dept. 17301 South Ridgeland Avenue Tinley Park, Illinois 60477

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

大会会 37 ZU06,



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Inventors:	Jack E. Caveney, et al.)	
U.S. Patent N	To.: 7,011,454)	Examiner: Chandrika Prasad
Issue Date:	March 14, 2006)	Group Art Unit:
For:	Reversible Fiber Optic Stub)	

CERTIFICATE OF MAILING

Certificate of Corrections Branch Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Date of Deposit: April 17, 2006

Attached Papers:

- 1) Request for Certificate of Correction (1 pg.);
- 2) Form PTO/SB/44 (1 pg.); and
- 3) Return Post Card.

I hereby certify that the attached papers or fee is being deposited as First Class Mail with the United States Post Office on the date indicated above and is addressed to Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

Signature of person mailing paper or fee

Panduit Corp. Legal Department - TP12 17301 S. Ridgeland Avenue Tinley Park, Illinois 60477-3091 (708) 532-1800, Ext. 1302

APT 97 2006.